

Date of Issue: November 2017

Affected Publication: API Specification 16A, *Specification for Drill-through Equipment*, Fourth Edition, April 2017

Errata 2

Section 5.3.5.4:

- In the newly inserted Section 5.3.5.4 from Errata 1, replace

1 mm ($\frac{1}{4}$ in.)

with

3 mm ($\frac{1}{8}$ in.)