

**Date of Issue:** April 2018

**Affected Publication:** API Specification 16A, *Specification for Drill-through Equipment*, Fourth Edition, April 2017

## Errata 3

*Section 4.3.4.3, Table 12:*

- The third row of the table should read:

79 (3 <sup>1</sup> / <sub>8</sub> )	79.40 (3.125)	160.32 (6.312)	29.60 (1.166)	125.40 (4.938)	59.9 (2.36)	BX-154	4
--	------------------	-------------------	------------------	-------------------	----------------	--------	---

*Section 4.3.4.3, Table 13:*

- The fourth row of the table should read:

78 (3 <sup>1</sup> / <sub>16</sub> )	77.80 (3.063)	193.68 (7.625)	30.40 (1.197)	158.75 (6.250)	60.4 (2.38)	BX-154	5
---	------------------	-------------------	------------------	-------------------	----------------	--------	---

*Section D.2.2:*

- The second paragraph should read:

The manufacturer shall communicate any design changes resulting from a malfunction, or failure history, to every known equipment owner of the affected equipment. That notice shall be within 30 days after the design change.