

Date of Issue: November 2010

Affected Publication: API Recommended Practice 1109, *Marking Liquid Petroleum Pipeline Facilities*, Fourth Edition, October 2010

ERRATA

This errata corrects editorial errors in the fourth edition of API Recommended Practice 1109.

Page 5, Figure 2, (in the lower left) it should read:

“Casing Vents”

rather than

“Casting Vents”

A revised figure has been attached.




Figure 2—Examples of Cross Country Markers and Signs