

**Date of Issue:** May 2009

**Affected Publication:** API Specification 6A, *Specification for Wellhead and Christmas Tree Equipment*, Nineteenth Edition, July 2004

## ERRATA 5

*This errata corrects editorial errors in the 19th Edition of API 6A.*

*Page 406, Table 3, change language in reference "C" from:*

"low allow"

to

"low alloy"

*Page 416, Section P.3.4, change reference from:*

"AMS-H-6875F"

to

"AMS-H-6875"