

Date of Issue: September 2012

Affected Publication: API Recommended Practice 1102, *Steel Pipelines Crossing Railroads and Highways*, Seventh Edition, December 2007

ERRATA 3

(includes Errata 1, November 2008 and Errata 2, May 2010)

This errata corrects editorial errors in the seventh edition of API Recommended Practice 1102.

Section 2.3.12, the defined term should read:

pipe jacking with auger boring

Figure 16, the vertical axis should read:

Highway stiffness factor for cyclic
longitudinal stress, K_{Lh}

Section B.2.1, the eleventh item in Step A should read:

Wall thickness, t_w