

Date of Issue: September 2011

Affected Publication: *MPMS* Chapter 11.2—Part 4—*Temperature Correction for the Volume of NGL and LPG Tables 23E, 24E, 53E, 54E, 59E, and 60E*, First Edition, September 2007

ERRATA

On page 1, Section 0 Implementation Guidelines, first sentence:

Please note that The Standard/Technical Publication, Chapter 11.2.4 does **not** supersede API *MPMS* Chapter 11.2.2/11.2.2M.